
Engineering Drawing Tutorial

*Engineering Drawing
Tutorial*

*Downloaded from
evoluir.abar.org.br by
Bartlett & Nathen*

INTRODUCTION: WHY MASTERING ENGINEERING DRAWING MATTERS

Engineering drawing is the universal language of engineers and manufacturers. Whether you are a mechanical, civil, or electrical engineer, the ability to read, interpret, and create precise technical drawings is a non-negotiable skill. An **Engineering Drawing Tutorial** that starts from

fundamentals can help you bridge the gap between a conceptual design and a finished product. In this guide, we will walk through the core concepts, tools, and techniques you need to produce clear, accurate drawings that communicate your ideas effectively. We will cover everything from line types and dimensioning rules to modern CAD workflows and common pitfalls to avoid. By the end, you will have a solid foundation to create and understand engineering drawings with confidence.

DRAWING?

An engineering drawing is a detailed graphical representation of an object or structure that conveys all the information required for its manufacture, assembly, or construction. Unlike an artistic sketch, an engineering drawing must be unambiguous, dimensionally accurate, and follow standard conventions. It serves as a contract between designers, engineers, and fabricators, ensuring that every party sees the same information.

In this **Engineering Drawing Tutorial**, we will adopt a systematic approach. Start by understanding the purpose: to provide a complete specification using views, dimensions, tolerances, and

notes. A **WHAT IS AN ENGINEERING** drawing is a visual communication tool that eliminates guesswork and reduces errors on the shop floor.

Key Elements of an Engineering Drawing

- **Views:** Orthographic projections (front, top, side) or isometric views show the shape from multiple angles.
- **Dimensions and Tolerances:** Numerical values that define size and allowable variations.
- **Title Block:** Contains drawing number, scale, date, drafter name,

and revision history.

- **Notes and Symbols:** Include surface finish requirements, material specifications, and welding symbols.

ESSENTIAL TOOLS FOR MANUAL DRAFTING

Even with the dominance of CAD software, understanding manual drafting tools helps you appreciate the precision expected in technical drawings. Here are the essentials you should know for any serious **Engineering Drawing Tutorial**.

- **Drawing Board:** A flat, stable surface with a T-square guide for horizontal lines.
- **Set Square (Triangles):** 45° and

30°/60° triangles for drawing perpendicular and angled lines.

- **Compass and Dividers:** For arcs, circles, and transferring measurements.
- **Scale Ruler:** Used for drawing to scale (e.g., 1:2, 1:5).
- **Pencils and Erasers:** Hard pencils (H, 2H) for light construction lines; softer pencils (HB, B) for final outlines.
- **Templates and Stencils:** For standard symbols, geometric shapes, and lettering.

TYPES OF LINES IN ENGINEERING DRAWINGS

Lines are the alphabet of technical drawing. Each type has a specific meaning, and using them correctly is a

key lesson in any **Engineering Drawing Tutorial**.

1. **Continuous Thick Line:** Visible outlines and edges.
2. **Continuous Thin Line:** Dimension lines, extension lines, hatching, and leader lines.
3. **Dashed Line (Medium Thickness):** Hidden edges or features not directly visible.
4. **Chain Thin Line (Center Line):** Indicates axes of symmetry, centers of circles, and paths of motion.
5. **Chain Thick Line:** Indicates cutting planes for sectional views.
6. **Ruled Thin Line with Zigzag:** Used for long break lines.

Mastering line types ensures your

drawing communicates clearly. For example, confusing a hidden line with a center line could lead to a part being manufactured incorrectly.

ORTHOGRAPHIC PROJECTION: THE CORNERSTONE OF TECHNICAL DRAWING

Orthographic projection is the method used to represent a 3D object on a 2D plane using multiple views. The most common arrangement is first-angle or third-angle projection. In this **Engineering Drawing Tutorial**, we focus on third-angle projection, which is widely adopted in North America and many other regions.

Creating Standard Views

Imagine an object placed in a glass box. The six principal views are: front, top, bottom, right side, left side, and rear. For most drawings, three views suffice: front, top, and right side. Follow these steps:

- Choose the front view that shows the most features.
- Project the top view directly above the front view.
- Project the right side view directly to the right of the front view.
- Align views carefully so that features correspond vertically and

horizontally.

Practice this projection by sketching simple blocks first. An effective **Engineering Drawing Tutorial** always emphasizes alignment and proportion.

First-Angle vs. Third-Angle Projection

In first-angle projection (common in Europe), the object lies between the viewer and the projection plane; the top view is placed below the front view. In third-angle projection, the projection plane lies between the object and the viewer; the top view is above the front

view. Always indicate the projection symbol in your title block.

ISOMETRIC AND PICTORIAL DRAWINGS

While orthographic views are precise for manufacturing, isometric drawings help stakeholders visualize the finished product. Isometric drawing uses a 30-degree angle from the horizontal for both depth and width axes, maintaining parallel lines and true scale along each axis. This **Engineering Drawing Tutorial** recommends starting with isometric sketches to brainstorm before creating detailed orthographic sheets.

- Draw a horizontal baseline.
- Draw three axes: one vertical, two at 30° to the horizontal.

- Measure along these axes to construct the object's dimensions.
- Use ellipses to represent circles that are not aligned with the isometric planes.

DIMENSIONING AND TOLERANCING

Dimensioning is where a drawing moves from a sketch to a specification. Every dimension must be clear, unambiguous, and placed according to standard practices. In this **Engineering Drawing Tutorial**, we cover the essentials of dimensioning and tolerancing.

General Dimensioning Rules

- Never crowd dimensions; leave enough space between extension lines and the object.
- Place dimensions outside the view when possible, but inside if space allows.
- Use the same units (typically millimeters or inches) throughout.
- Chain dimensions only when necessary; base dimensions from a datum are often preferred for manufacturing.

- Include a leader line with an arrowhead pointing to the feature for notes and diameters.

Geometric Dimensioning and Tolerancing (GD&T)

GD&T is a more advanced system that controls the form, orientation, location, and runout of features. While a full **Engineering Drawing Tutorial** cannot cover every GD&T symbol here, you should understand the basic concept: tolerance is not only about size, but also

about shape and position. Common GD&T symbols include true position, flatness, parallelism, and perpendicularity. Modern drawings often call out GD&T to ensure interchangeability of parts.

SECTIONAL VIEWS AND AUXILIARY VIEWS

When an object has internal features that are not clear from exterior views, a sectional view (cross-section) is used. The cutting plane line indicates where the imaginary cut is made, and the section is hatched with thin lines at 45° angles.

- **Full Section:** Cuts entirely through the object.
- **Half Section:** Cuts one quarter,

showing both exterior and interior.

- **Revolved Section:** Shows the profile of a feature like a rib or spoke.
- **Removed Section:** Placed outside the view for clarity.

Auxiliary views are used to show the true shape of an inclined surface. They are projected perpendicular to the surface's edge view. Including these in your **Engineering Drawing Tutorial** practice will make you comfortable handling complex geometries.

STEPS TO CREATE AN ENGINEERING DRAWING FROM SCRATCH

Follow this step-by-step workflow to produce a professional drawing. This

outline is the heart of any practical **Engineering Drawing Tutorial**.

1. **Analyze the Object:** Understand its function, key features, and symmetry.
2. **Choose Views:** Decide which orthographic views best describe the object. Select the front view first.
3. **Establish Scale and Paper Size:** Use standard sheet sizes (A4, A3, etc.) and an appropriate scale (e.g., 1:1, 1:2, 1:5).
4. **Draw Construction Lines:** Light horizontal and vertical lines to block out the overall dimensions.
5. **Add Detailed Geometry:** Draw edges, curves, holes, and fillets. Use dashed lines for hidden

features.

6. **Apply Dimensions:** Add extension lines, dimension lines, and numerical values. Follow standard placement rules.
7. **Include Tolerances and Notes:** Specify allowable variations, surface finish, and material.
8. **Add Title Block and Borders:** Fill in drawing number, scale, date, and your name.
9. **Review and Revise:** Check for missing dimensions, conflicting information, and clarity.

COMMON MISTAKES IN ENGINEERING DRAWINGS

Even experienced drafters make errors. Learning from common mistakes is an essential part of any **Engineering**

Drawing Tutorial.

- **Over-Dimensioning:** Including more dimensions than necessary creates confusion. Use GD&T instead of redundant linear sizes.
- **Under-Dimensioning:** Missing a critical dimension leaves the manufacturer guessing.
- **Poor View Alignment:** Misaligned views cause misinterpretation of size and shape.
- **Inconsistent Line Types:** Using the wrong line weight or style can hide important details.
- **Crowded Notes:** Notes that overlap views or dimensions make the drawing hard to read.
- **Ignoring Standards:** Each

industry (e.g., ISO, ANSI, ASME) has specific conventions; deviating from them leads to errors.

TRANSITIONING FROM MANUAL DRAFTING TO CAD

Modern engineering drawings are largely created in computer-aided design (CAD) software like AutoCAD, SolidWorks, or Fusion 360. However, the principles from manual drafting remain foundational. In fact, a quality **Engineering Drawing Tutorial** often starts with manual techniques before introducing CAD. When you switch to CAD, you will still need to understand layers, line types, dimension styles, and orthographic projection – exactly the same concepts, just applied digitally.

Tips for CAD drafting:

- Use templates with predefined title blocks and layers.
- Leverage parametric modeling to update dimensions automatically.
- Generate views from 3D models to eliminate projection errors.
- Always check your plot/print preview for line thicknesses and scaling.

PRACTICAL TIPS FOR MASTERING

ENGINEERING DRAWING

To truly excel, incorporate these strategies into your practice sessions. This **Engineering Drawing Tutorial** will be most effective if you actively apply what you learn.

1. **Sketch Every Day:** Even a 10-minute sketch of a household object improves your observation and line work.
2. **Study**